

## **Important Warranty Information**

Please read prior to commencing fitment of this hub assembly.

- After removing the old unit and fitting the new hub onto the vehicle make sure that the driveshaft hub nut has been torqued to 490Nm.
- Then clear the fault codes already stored in the system.

If this is not done your ABS light may not cancel on test drive and if the part is returned to Britpart and no fault is found with it, the part will be returned to you and credit may be refused.