

Product Information



Please take time to read this information prior to fitment of DA2357HD – Heavy Duty TD5 Flywheel and Clutch kit.

When DA2357HD is fitted you may experience an increase in gearbox noise when the vehicle is running at idle. This noise can normally be attributed to transmission chatter and is common to diesel engine vehicles without Dual Mass Flywheels. TD5 engines can vary a lot in the amount they suffer from this problem which is generally dependant on the condition and wear of the vehicles gearbox. This transmission chatter is a characteristic of the part and will not affect the performance of it.

Please do not fit the part if you do not accept that there will be an increase in noise.